CRYING SHUTTERS

AL-V-A-039 Route 36, Wright's Crossing ca. 1890

The Crying Shutters Frame House was built circa 1890 by Anton Strutz. The house meets the standards of a typical rural residence found in Allegany County being a "L" shaped, two story, frame structure. However, features that are atypical of the common style of frame houses in the county include a three sectional entrance bay, the louvered shutters and the chamfered columns with scrolled brackets supporting the porch roof. The structure continues to be used as a residence and remains virtually the same as it appeared eighty five years ago.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAM	Ε		· ·			
HISTORIC						
AND/OR CO	OMMON	Crying Shu	utters			
2 LOCA	TION					
STREET & 1	NUMBER					
		Route 36			CONGRESCIONA	DICTRICT
CITY, TOW!	V	Wrights Co	rossing 🕹	L VICINITY OF	congressional Sixth	DISTRICT
STATE					COUNTY	
		Maryland			Allegany	
3 CLAS	SIFIC	ATION				
CATE	GORY	OWNERS	НІР	STATUS	I	PRESENT USE
DISTRI		PUBLIC		X OCCUPIED	AGRICULTU	
X.BUILDI STRUC		XPRIVATE		UNOCCUPIED	COMMERC	
SITE	IONE	BOTH	CQUISITION	WORK IN PROGRESS ACCESSIBLE	EDUCATION	
OBJEC	Т	_IN PROCESS		YES: RESTRICTED	GOVERNMI	
		BEING CONS	IDERED	YES: UNRESTRICTED	INDUSTRIA	-
				Xno	MILITARY	OTHER
4 OWN	ER OF	PROPER	RTY			
NAME						77 / 400 /
STREET & f		Robert J. (Groves		Telephone #:	77 4-6804
SIREELO		3273_Jon es	Dogs			
CITY, TOW		JZ/J_JUIIes	ROAD		STATE	, zip code
		Woodbine,	X	_ VICINITY OF	Maryla d	21797
5 LOCA	TION	OF LEGA	AL DESC	RIPTION	Liber #: 4	33
COURTHOL	JSE.				Folio #:	3 0
REGISTRY	OF DEEDS, E	TC. A11e	gany Count	y Courthouse		
STREET &	NUMBER	30 17	ashington	Street		
CITY, TOW	N		asiiingcon	Screec	STATE	
		Cumb	erland,		Mary	land
6 REPR	ESEN	TATION	IN EXIST	TING SURVEYS		
TITLE						
·						
DATE				FEDERAL	STATECOUNTY	LOCAL
DEPOSITO			····			
SURVEY RE						
CITY, TOW					STATE	



CONDITION

CHECK ONE

CHECK ONE

12-V-A-03

__EXCELLENT

__DETERIORATED

__UNALTERED

X ORIGINAL SITE

_GOOD

__RUINS
__UNEXPOSED

__MOVED DATE_

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

"Crying Shutters" is located on the east side of Route 36 in Frostburg, Allegany County.

"Crying Shutters" is a two story, five bay wide, rectangular structure that has been covered with weatherboard. Two frame additions are located on the west side of the building. The entire structure rests on a low foundation that is part cement block and part stone. The roof is gabled and is covered with tin with a boxed cornice and returns. Windows in the house are a combination of two over two and four over four lights with cornices and louvered shutters. The main entrance is located in a three sided entrance hall and includes a carved door with a window. This entrance is covered by a five bay hipped roof porch that is supported by scrolled brackets and chamfered columns. A second side entrance is also covered by a one bay entrance porch. Three original corbeled brick chimneys are located in the interior of the building.

"Crying Shutters" is in fair condition and retains much of its original fabric and appearance.

8 SIGNIFICANCE

1-VA-039

PERIOD	AF	REAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW		
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
1700-1799	ART	ENGINEERING	MUSIC	THEATER
X1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
1900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
		INVENTION		
SPECIFIC DAT	ca. 1890	BUILDER/ARC	HITECT Anton Strutz	

STATEMENT OF SIGNIFICANCE

The Crying Shutters frame house was built circa 1890 by Anton Strutz as a rather fashionable residence for his family. The structure is typical of the basic style of frame house found in Allegany County and more specifically the style of residence found in this portion of Route 36. The house was built at about the same time as several other residences immediately surrounding the structure, however; this house remains virtually the same as it was eighty five years ago. Features that are atypical of the common style of frame house in the County include the three sectional entrance orial, the louvered shutters and the chamfered columns with scrolled brackets supporting the porch roof.

The house is presently being used as a residence and because of the house retaining much of its original appearance, it is a cultural and architectural document of a way of life once found in Allegany County.

MAJOR BIBLIOGRAPHICAL REFERENCES

12-V-A-039

DATE

12/7/76 TELEPHONE

777-8991

Maryland

STATE

Allegany County Land Records, Cumberland, Maryland

CONTINUE ON SEPARATI	SHEET IF NECESSARY	
GEOGRAPHICAL DA	TA	
ACREAGE OF NOMINATED PROPERTY	.503 acres	
		# 1 . A
VERBAL BOUNDARY DESCRIPT	ION	
LIST ALL STATES AND CO	UNTIES FOR PROPERTIES OVERLAPPING STA	TE OR COUNTY BOUNDARIES
STATE	COUNTY	
STATE	COUNTY	
FORM PREPARED B	Y	
NAME / TITLE		
John Nelson	Joan Baldwin & Steve Beale	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

Allegany County Historic Sites Survey

507 National Highway

LaVale.

ORGANIZATION

CITY OR TOWN


STREET & NUMBER

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

INVENTORY NO. AI-V-A-039	433/30
DATE: 11/20/76	Lot 21
REMCDETING: Drastic, moderate, minor	. 503 Acres
NAME OF PROPERTY: Crying Shutters	, 503 Acre
LOCATION OF PROPERTY: Rt.36	
DIRECTION DWELLING FACES: 3ast	entered in the sufficiency and the discussion and the staff has highly discussion may be also as a supply discussion as a discussion of the sufficiency and the supply of the sufficiency and the supply of the sufficiency and the supply of the sufficiency and the sufficiency and the supply of the supply
NAME OF OWNER: ROBERT-J. Groves	224-6804
ADDRESS: 3273 Jones Rd	
Woodbine M.D. 2179	77
STORIES: 1() 2(\(\) 3() 4() 5() 6() BAYS: 1() 2() 3() 4()5(ブ6()7()()
WINGS, ADDITIONS: rear sned root + gable root addition	
Dwelling Shape: (square, cross, rectangular)	
WALL CONSTRUCTION:	
() FRAME: Bevel, clapboard, weatherboard, wood shingles, board () BRICK: Bond type- common, English, Flemish. Sketch variant () STONE: Bond type- rubble, ashlar (random or regular), quoin () LOG () Other: Coverings	S.
WALL FEATURES: BELT COURSE, PILASTERS, CTHERS FOUNDATIONS: HIGH, LOW, BRICK, STONE replaced Cement block WATER TABLE: NONE, PLAIN, BEVELED, MOULDED BRICK	K.
WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/9() o COVERED SHUTTERS pegged () nailed() wide () narrow (ther(5 cemics) mitred() pediment()
ENTRANCE, DOORS: LOCATION: Sast Scorth HARDWARE: original() replaced() FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN Paneled, Verticle, Horizontal Boards	u moleru-
CCRNICE, BARGE, EAVES: (crown, fascia, soffit, bed) original() replaced() Rafter Ends, Modillions,	Dentils, Frieze, Architrave
ROOF: GABLE FRONT, GABLE FLANK, HIP, SHED, MANSARD, GAMBREL, FLAT MATERIAL: wood shingles, slate, tin, asphalt original()	, DORMERS #
FORCHES: SHAPE OF ROOF - shed() hip(/ gable()	
CHIMNEYS: NUMBER 3 BRICK() STONE() CORBELED() original LOCATION: Flush end() Inside end() Outside end()	() replaced () Central() Interior ()
ARCHES: Door and window: Keystone, Flat, Segmental, Semicircular	
COMMENTS: Use - rasidence Significance - Ard Pate Constructed - 1890'S Anton Strutz Condition - Fair	





Al-V-A-039 Crying shutters Rt. 36; west side Frostburg 11120176 AGAN NELSON northwest



AI-V-A-039
Crying Shutters
Rt. 36, WEST SIDE
Frostburg
11/20176
Qohn Nelsen
nertheast